

Checking Resistance of Solenoid B through the Harness

- Ignition OFF
- Disconnect the Transmission Harness Connector
- Using a multi-meter pin out between P & N for a resistance reading, the expected value is 4.5 Ohms (Cold)

Note: Add 0.1 Ohms per FT of length for 18 Gauge wire.

